## interphone

## F5MC firmware release note

Rev.	Date	Description
R110	08 Jun 2015	Fix: increased compatibility with BMW Navigator V device.
R106	25 Feb 2015	<ul> <li>Mod: new improved noise suppression.</li> <li>Mod: changed low battery warning timeout to 20 minutes and very-low battery to 5 minutes.</li> </ul>
R104	20 Jun 2014	Mod: increased FM radio receiver sensitivity.
R102	23 May 2014	<ul> <li>Fix: bug fix for microphone muted, when incoming phone call during FM radio listening.</li> </ul>
R100	13 May 2014	<ul> <li>Mod: improved noise suppression.</li> <li>Mod: changed sensitivity of automatic volume control.</li> <li>Mod: vocal help now stops during phonecall ringtone.</li> <li>Mod: erasing pairing (from setup menu) now will end with unit in pairing mode.</li> <li>Mod: with unit off, now is possible to select the language, powering on the unit and keep pressed MFB (as previous XT range).</li> <li>Fix: bug fix with Czeck lang.</li> <li>Fix: fixed error message for intercom connection when only one another unit is paired.</li> <li>Fix: minor bugfix.</li> </ul>
R91/R91C	03 Mar 2014	Fix: minor bugfix.