

# interphone

## F4MC firmware release note

Rev.	Date	Description
<b>R110</b>	08 Jun 2015	<ul style="list-style-type: none"><li>• Fix: increased compatibility with BMW Navigator V device.</li></ul>
<b>R106</b>	25 Feb 2015	<ul style="list-style-type: none"><li>• Mod: new improved noise suppression.</li><li>• Mod: changed low battery warning timeout to 20 minutes and very-low battery to 5 minutes.</li></ul>
<b>R104</b>	20 Jun 2014	<ul style="list-style-type: none"><li>• Mod: increased FM radio receiver sensitivity.</li></ul>
<b>R102</b>	23 May 2014	<ul style="list-style-type: none"><li>• Fix: bug fix for microphone muted, when incoming phone call during FM radio listening.</li></ul>
<b>R100</b>	13 May 2014	<ul style="list-style-type: none"><li>• Mod: improved noise suppression.</li><li>• Mod: changed sensitivity of automatic volume control.</li><li>• Mod: vocal help now stops during phonecall ringtone.</li><li>• Mod: erasing pairing (from setup menu) now will end with unit in pairing mode.</li><li>• Mod: with unit off, now is possible to select the language, powering on the unit and keep pressed MFB (as previous XT range).</li><li>• Fix: bug fix with Czeck lang.</li><li>• Fix: fixed error message for intercom connection when only one another unit is paired.</li><li>• Fix: minor bugfix.</li></ul>
<b>R91/R91C</b>	03 Mar 2014	<ul style="list-style-type: none"><li>• Fix: minor bugfix.</li></ul>